INSTRUCTIONS


Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

-CERTIFIED CORNER RECORDATION

Corner 1/4 cor. between Sec . 34 & 35 T. 260 R. 30W P.M.M. Wincoln

BLM brass Found COP



Cross Index No. X-D T. 2GN R.30W PMM

corner this sheet