INSTRUCTIONS 2. Description of exten ce found, note discrepancies in the record, state method of establishin CHEBRIA. ories set to perpetuate the corner pu 4. Sketch or curner, show all pertinent data which can best be shown in a sketch example, curner m topography lies, position of accessories, stc. 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana. 6. Fill in Cross lades & Section Diagram at buttom of sheet. CERTIFIED CORNER RECORDATION Corner <u>C-N-N-SW 1/256 Sec. 24</u> T. 30N R. 34W P.M.M. LINCOLN __County No record or evidence of corner bing previously set. I position corner from found section and quarter corners and as shown on the Certificate of Survey as filed and of record in the Lincoln Co. Courthouse. I set a 3" alum. cap for corner position, from which: A 20" cedar bears S66° W, 13.1', scribed C-N-N-SW 1/256 S24 BT A 24" cedar bears N24 $\frac{1}{2}$ ° W, 19.4', scribed C-N-N-SW 1/256 S24 BT Painted red bands around BT's and painted the blazes red. Posted BT, attention, and Locations signs. 10-24 C-N.N.6W 1/250 WARREN 1984 20"CEDAR that this Corner Record correctly represents work performed or under by direction in compliance with the "Corner 24 CEDAR Employer: BOCK, MOUNTAIN SURVEYORS SKETCH OF CORNER 24 Office of Clerk and Recorder, County of LINCOLN _ day of 1984