## INSTRUCTIONS

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

Certification must be signed and sealed by Registered Land Surveyor in State of Montana

6. Fill in Cross Index & Scelton Diagram at bottom of sheet,

## CERTIFIED CORNER RECORDATION

<u>CS 1/16 Section 22</u> Т. <u>32N.</u> R. <u>3LW:</u> Р.М.М. County

## I. Davis Surveying Inc. 1986

I set a  $3\frac{1}{4}$ " diam. Aluminum Cap on a 5/8" diam. x 4' long rebar driven into the ground. Stamped;

> CS 4,6 132N R34W 522

49755 1984

from which,
A 6" red fir bears N.15°W. 14.60 feet from center of tree. Scribed CS 1/16 S22 BT. Painted a red band around tree. Notched at root crown. A 6" red fir bears N.44°E. 15.40 feet from center of tree. Scribed CS 1/16 S22 BT. Painted a red band around tree. Notched at root crown. Placed BT sign #54-3 on front and warning sign #54-9 on back of trees. Set a steel post 1' north of corner.

Ken E. Davis Davis Tom certlfy th

## SKETCH OF CORNER

Davis Surveying Inc. Office of Clerk and Recorder, County of This "corner day of 1986 record" was filed for record on the ... was noted on the cross-index plat and is assigned page No book No.

- corner this sheet

epresents work pertormed