INSTRUCTIONS

- COCDETA.

nest and accessuries set to perpetuate the corner position.

- 4. Sheich or corner, show all pertinent data which can best be shown in a sketch example, corn Service or Country
 topography lies, position of accessories, gic.
 Usrtification must be signed and seeind by Hegistered Land Surveyor in State of Montans.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner N 1/16 Sec. 31 T. 34N ___R. __25W LINCOLN _County

No record or evidence of corner being previously set.

I position corner from found section and quarter corners and as shown on the Certificate of Survey as file and as of record in the Lincoln Co. Courthouse.

I set a 3" alum. cap for corner position, from which:

A 13" fir bears S.19°30'E., 42.9' scribed N 1/16 S32 BT An 8" fir bears S.81° W., 5.3' scribed N 1/16 S31 BT

Painted red bands around BT's and painted blazes red. Posted BT, Attention, and Location signs. 6' metal post w/survey monument sticker along side cap.



