#### INSTRUCTIONS

- 1. Original as
- 4. Sketch or corner, show all partinent data which can best be shown in a sketch example, corn
- topography ties, position of accessories, etc. 5. Certification must be signed and sealed by 5. Certification must be signed and sealed by Registered Lan 6. Fill in Cross Index & Section Diagram at bottom of sheet. ed by Registered Land Surveyor in State of Montana.

# **CERTIFIED CORNER RECORDATION**

34N R. 26W Corner SE 1/16 Section 31 LINCOLN County

### **RECORD:**

None found.

## FOUND:

No corner monument found and no BT's.

# MAINTENANCE:

Set a  $3\frac{1}{4}$ " Aluminum Cap on a 30" Aluminum Rod. 6" Tamarack S13 W 44.9' scribed SE 1/16 S31 BT. 5" Tamarack S82 E 34.8' scribed SE 1/16 S31 BT. Steel Post South 3'.

All trees have location tags and Attention or Land Surveying Monument signs on the back side - ring painted around tree. Declination used 195



