INSTRUCTIONS

1. Original and/or subsequence found, note discrepancies in the record, state method of establishing

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

-CERTIFIED CORNER RECORDATION

Corner Sec. Con Sections 33,23,20,27 T. 3600 R. 2600) P.M.M. Lincoln

BLM brass cap Found

See C. of S. No. 918 for adjacent corners ..

Doug fir Doug fir	CERTIFICATION
CAD SUR	certify the information shown herein is true and correct.
T36NOR26WN	Signature Ground Party Chief
<u>əə</u> ə <u>ə</u> ə7 ə6	certify that this Corner Record correctly represents work performe by ne or under by direction in compliance with the "Corne
1960	Recordation Act" (70-22-101, et seq., M.D.A.) Oldwardiacold Signature of Surfeyor & Seal
BLM 3320	Signature of Surveyor & Scal Date: 7-13-81 Reg. No. 0285ES
SKETCH OF CORNER 8" Lodge pole pine	Employer:
Office of Clerk and Recorder, County of Lincoln	. This ''corner

 $_{-}$ day of 19 ,

· corner this sheet

Cross Index No. R-17 T. 36N R.3CU) PMM

record" was filed for record on the July 17th