INSTRUCTIONS

nt record used to evaluate the corner position. ound, note discrepancies in the record, state method of estab 2. Description of evid corners.

aries set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

Certification must be signed and scaled by Registereo Lar
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

NW-1/16 Sec. 23 T. <u>36N</u> R. <u>28W</u> Corner_ P.M.M. Lincoln

None


II. None

Drove a 3/4" x 24" rod into ground with a 3-1/4" alum. III. cap for corner position.

Established BT's as follows:
7" fir bears N.76°E., 38.2', scribed NW-1/16 S23 BT
11" fir bears S.41°W., 33.10', scribed NW-1/16 S23 BT

Posted BT, Attention and Land Monument signs; painted blazes red; drove steel post in ground along side . . corner monument.

For monument location, see the Certificate of Survey on




7" FIR N.76°E. 38.2 **SKETCH OF CORNER**

CERTIFICATION certify the information shown herein is true and correct. Signature Ground Party Chief H. Gene Warren certify that this Corner Record correctly represents work performed by me or under by direction in compliance Recordation Act" (70-22-101, et seq., M.D.A.) 11-85 Reg. No. 2734S ROCKY MOUNTAIN SURVEYORS

Office of Clerk and Recorder, County of Lincoln

was noted on the cross-index plat and is assigned page No. \perp book No. .

018 T. 36N R. 28W PMM



· - corner this sheet