INSTRUCTIONS

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- 6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 1131 CORI SEC 7 T36N R31W LINCOLN CO.

FND Z'/z" F.S. DISK BRASS CAP ON Z" STEEL PIPE 0.60 ABOVE GRD LEANING 45° NORTH I OFF RIGHT EDGE OF BANK STAMPED

1-1131

SET ALUM FS DISKS W/ METAL SIGNS STAMPED

- 1) 335°W 17.12' DIST
- 2) N72°W 19.64' DIST.


79755

1993

T36N R31W S7 RM CORI HES 1131

SET STEEL POSTS W/ METAL. SIGNS

- D 588°E 0.40' DIST
- Z) NZ5°W 0.80' DIST



CERTIFICATION certify the information shown herein is true and correct. Signature Ground Party Chief Thomas E. Sands certify that this Corner Record correctly represents work performed 7/23/93 Reg. No. 7975-S Sands Surveying, Inc.

SKETCH OF CORNER Office of Clerk and Recorder, County of . This "corner 27, 1993 day of 19, record" was filed for record on the was noted on the cross-index plat and is assigned page No. M. County Official book No.

Cross Index Not ES 1/31-1' T. 36N R. 3/W PMM

