- 3. Description of monument and accessories set to perpetuate the corner position.
 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 6. Fill in Cross Index 5. Sealed Disgraphy of best and of the control of the control

Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 487 CORI SEC 7 T36N R31W Lincoln Co.

FNO 5/8" REBAR BY 1975-S ON LINE PER COS ZOOIA NZ5°OZ'IZ"W 66.00' DIST.

WET ALUM WISK STAMPED D NZ5°02'12"W 103.82' DIST

79755 1993

T36N R31W 37 RM CORI HES 487

ALUM CERTIFICATION DISK O certify the information shown herein is true and correct. REBAR Signature Ground Party Chief Thomas E. Sands certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.) <u>Sands Surveying, Inc.</u> **SKETCH OF CORNER** Office of Clerk and Recorder, County of . This "corner 27,1993 day of 19, record" was filed for record on the _ was noted on the cross-index plat and is assigned page No.

book No.

M. Cumming County Official

Cross Index No. HE\$487-1 T. 3/11/ R. 3/11/ PMM