i. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 485 COR 3 SEC 6 T36N R31W LINCOLN CO.

FNO OLD STONE MON W/"X" CUT 0.5' ABOVE GRO. & "3 HES 485" WRITTEN ON SOUTH SIDE

- FNO BARB WIRE FX 1.5' SOUTH OF STONE. MON. & ZI.Z' DIST SZOOW OF MON.
- FNO BARB WIRE FX COR. O.10' SOUTH PROPERTY LINE ; BEARING 581°W ON PROPERTY LINE Z6.3' FROM STONE MON.

SET (Z) REF. MON. (RM.); ALUM ROO W 3'/4" ALUM FS. CAP STAMPED "HES 485 COR 3" 1) SZIOW 19.82' OIST.

z) 581°W 21.36' DIST

SET STEEL POSTS W/ DECALS 54-7 \$ 54-9

D WEST. 0.50' DIST

DWEST ZO. SZ' DIST

3) 320°W/ 0.75' DIST

4) SZOOW ZI. 96' WIST.

SKETCH OF CORNER

Signature Ground Party Chief Thomas E. Sands certify that this Corner Record correctly represents work performed 7/23/93 Reg. No. 7975-S Sands Surveying, Inc.

CERTIFICATION

Office of Clerk and Recorder, County of June . This "corner	Sec.	
record' was filed for record on the duly 27, 1993 day of 19,		
was noted on the cross-index plat and is assigned page No, in		
book No County Official County Official		
Cross Index No/HES 485.3 T. J.W. R. 3/W. PMM	• - corner t	his sheet