

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

topography ites, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.


6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

-CERTIFIED CORNER RECORDATION

Corner South 1/4 corner Section 33 T. 37N R. 27W P.M.M. Lincoln Record: Set a post 3' long x 3" Sq. 24" in the ground from which:

a pine H" diam. bears N.41030'w. 94 lks. 38" dram Dears S. 520€. 54 lks.

SET-BRASS CAP, ____



Office of Clerk and Recorder, County of Lincoln record" was filed for record on the Jehnuary : 17th day of 1943 was noted on the cross-index plat and is assigned page No. 1546 Eleanor L. Hougher by Betty f. book No. 🚣

Cross Index No. 2-11 T. 370 R. 276) PMM

corner this sheet