## INSTRUCTIONS

and, note discrepancies in the record, state method of establishing lost or obliterated

4. Skeich or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ites, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.


6. Fill in Cross Index & Section Diagram at bottom of sheet.


## CERTIFIED CORNER RECORDATION

County

- (1) No previous record or evidence.
- (2) Monument and accessories set to perpetuate corner position

Set a standard 3% inch Forest Service alum. cap on a 5/8 inch rod 28 inches into the ground; from which:
A 7 inch fir bears S 27½ E 17.05 feet scribed E 1/16 S11 BT
A 8 inch fir bears N 26 E 20.30 feet scribed E 1/16 S2 BT Set a U.S.D.A. steel post 3 feet north of corner





· corner this sheet

- PMM