- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking pography ties, position of accessories, etc.

  Certification must be signed and sealed by Registered Land Surveyor in State of Montana. topography ties, position of acc
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION


HES GOS CORZ SECZI TSIN R3IN LINCOLN CO.

FND OLD STONE MON W/"X" CUT & "Z HESSOS" WRITTEN ON SIDE

SET BT II" SPRUCE NIOOW 8.60' DIST SCRIBED "XBT" SET BT 10"LODGEPOLE PINE SIZON 6.60' DIST. SCRIBED "THES 503" SET STEEL POSTS W/ DECALS 54.2 \$ D NORTH 1.1' DIST Z) WEST 1.2' DIST

Thomas E. Sands certify that this Corner Record correctly representations pertormed by me or under by direction in compliance with the Corner Recordation Act 70.22-101, et seq.; M.D.A. 7/23/93 Reg. No. \_ 7975**-**S Sands Surveying, Inc.

SKETCH OF CORNER	Employer.
Office of Clerk and Recorder, County of	. This "corner
record" was filed for record on the	day of 19 ,
was noted on the cross-index plat and is assigned page No. $5$	
book No Mal M. Cumm	ingo By DB
County Offic	
1 Company HES503.7 -	47// - 2/1//



112

corner this sheet