INSTRUCTIONS

- Sketch or corner, show all pertinent data topography ties, position of accessories, etc. show all pertinent data which can best be shown in a sketch example, corner marking,
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 481 CORS SEC 32 T37N R31N/ LINCOLN CO.

FND OLD STONE MON W/X" CUT 08' ABOVE GRD & "SHES 481" WRITTEN ON SW SIDE 6 HES 478" WRITTEN ON SE SIDE

FND OLD BT IZ" SPRUCE S63°W 14.04' DIST RESCRIBED "X BT"

FNO OLD BT 10" SPRUCE N30'E 13.73' DIST SCRIBED "SHES 481" NO TAGS FND OLD BT 10" PINE STUMP 566°E 11.22', DIST SCRIBED "SHES 479" & "WHES 481" BT

SET STEEL POSTS W/ DECALS 52-4 & 52-9 D SIGN 1.00' DIST.

CERTIFICATION GBT certify the information shown herein is true and correct. Signature Ground Party Chief Thomas E. Sands certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the Revordation Act (70-22-101, et seq., M.D.A.) 7/23/93 Reg. No. __ 7975-S Sands Surveying, Inc. SKETCH OF CORNER Office of Clerk and Recorder, County of Sime . This "corner 27,1993 day of 19, record" was filed for record on the was noted on the cross-index plat and is assigned page No book No.

Cross Index No. HES481-6 T. 37N R. 3/W PMM