INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner ___C-S-N-S 1/256 BT___ Sec. 22 T. 26N ___ R. __29W__ . P.M.M. __Lincoln__ _____ County

Set 5/8" X 24" capped steel pin stamped JHN 4661S

Set 6" Douglas Fir bearing tree scribed C-S-N-S 1/256 BT from which the corner bears S74°W 24.3 ft.

Set 16" Douglas Fir bearing Tree scribed C-S-N-S 1/256 BT from which the corner bears S 01°W 38.2 ft.

Set a location poster on a 10" Douglas Fir from which the corner bears N 56°W 8.7 ft.

SKETCH OF CORNER

CERTIFICATION

I, David Stanley certify the information shown herein is true and correct.

Signature Signature Ground Party Chief

Jack H. Ninneman
I, certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

_Signature_ Signature of Surveyor & Seal
4661S

Date: _____ Reg. No. _____

Employer: __Ninneman Engineering Inc.__

Office of Clerk and Recorder, County of __LINCOLN__ . This "corner record" was filed for record on the __OCTOBER 20__ day of 1983, was noted on the cross-index plat and is assigned page No. __2360__ , in book No. _____

Janet BF Siegel by Betty L. Conces
County Official ___deputy___

Cross Index No. ____22____ T. __26N.__ R. __29W__ PMM

Sec. 22

• - corner this sheet