INSTRUCTIONS
1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner $S\frac{1}{16}$ S15/S14 . . . T 33N R 26W P.M.M. _Lincoln_ County

There is no previous record of this corner having been set.

Set a 2 in × 30 in. Aluminium Pipe with a $3\frac{1}{2}$ in diameter Aluminium cap stamped as shown and raised a collar of stone,

From which

A 11" Fir bears N 50° W , 44.80 ft. scribed "$S\frac{1}{16}$ S15 BT"

A 12" Pine bears S 54° W , 10.00 ft. " "$S\frac{1}{16}$ S15 BT"

SKETCH OF CORNER

(USDA FOREST SERVICE
T 33N $S\frac{1}{16}$ R 26 W
S15 | S14
1981
SMITH 47405
UNLAWFUL TO DISTURB)

CERTIFICATION

I, _Thomas Van Slyke_ certify the information shown herein is true and correct.

Thomas Van Slyke
Signature Ground Party Chief

I, _S. R. Smith_
certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

S R Smith
Signature of Surveyor & Seal

Date: _____ Reg. No. **47405**

Employer: _SMITH SURVEYING CO._

Office of Clerk and Recorder, County of _Lincoln_ . This "corner record" was filed for record on the _July 28th_ day of 1982

was noted on the cross-index plat and is assigned page No. _1745_ , in

book No. _____

Eleanor L. Vaughn by Betty L. Conces
County Official   deputy

Cross Index No. _K-17_ T 33N R 26W PMM

Sec. _15_

• - corner this sheet

Basis of Bearings: Solar Observation near 1/4 10   9/10

(1745)

(N89°45'E 2650.56'-GLO)   (N89°45'E 2650.56'-GLO)

S89°54'06"E 2654.24'   ▷◁ N89°59'46"E 2652.55 BLM
1326.28'   1326.28'

Reset from broken BLM Monument

N89°59'30"E   2649.72
1324.96'   1324.96'

2645.29'   1323.65'   1323.65' BLM
N89°59'14"E   5292.59

S89°59'05"E   2647.97

(S89°59'E 2647.26'-GLO)   (S89°59'E 2647.26'-GLO)
N89°56'44"E 2646.16'   S89°57'14"E 2648.64 BLM
1323.08'   1323.08' BLM

5284.98'   2644.36'
2641.78'

S89°54'03"E   5284.38'
1317.14'   1317.14'   2650.10' DKM Br.Cap

2642.82'
1321.41'

1319.73'   1319.72'
S89°53'33"E   2639.45'   S89°53'48"E   2650.81'

1322.31'   1322.31'
S89°53'04"E   2644.62' DKM   S89°53'33"E 2651.53' BLM
(N89°55'E 2646.60'-GLO) Brass Cap (N89°55'E 2646.60'-GLO)