INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner NE 1/16 Section 7 T. 33N R. 26W P.M.M. LINCOLN County

RECORD:

None found.

FOUND:

No corner monument and no BT's.

MAINTENANCE:

Set 3¼" Aluminum Cap on a 30" Aluminum Rod.
7" Lodgepole Pine N07°E 5.7' scribed NE 1/16 S7 BT.
9" Fir N83°E 16.3' scribed NE 1/16 S7 BT.
Steel post North 3'.

All trees have location tags and Attention or Land Surveying Monument signs on the back side - ring painted around tree.
Declination used 19½°.

SKETCH OF CORNER

CERTIFICATION

I, Glenn M. Knodle certify the information shown herein is true and correct.

Glenn M Knodle
Signature Ground Party Chief

I, H. Gene Warren 2734 S certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

H Gene Warren
Signature of Surveyor & Seal

STATE OF MONTANA H. GENE WARREN 2734 S REGISTERED LAND SURVEYOR

Date: 7-1-88 Reg. No. 27345

Employer: Rocky Mountain Surveyors

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 29, 1988 day of 19, was noted on the cross-index plat and is assigned page No. 3874, in book No. _____

Janet BF Sigel by Bill Bartlett Dep.
County Official

Sec. 7

Cross Index No. F-4 T. 33N R. 26W PMM

• - corner this sheet