INSTRUCTIONS

1. Original and/or subse[illegible]record used to evaluate the corner position.
2. Description of evidenc[illegible]d, note discrepancies in the record, state method of establish[illegible]t or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 1/4 Corner Sections 5 & 8 T. 35N R. 27W P.M.M. Lincoln County

Found BLM brass cap





SKETCH OF CORNER

CERTIFICATION

I, _____ certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Marquardt certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

D K Marquardt
Signature of Surveyor & Seal

Date: 12/11/81 Reg. No. 2989ES

Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 8th day of February 19[illegible] was noted on the cross-index plat and is assigned page No. 1515, in book No. 1

Eleanor L. Vaughn by Betty L. Conces deputy
County Official

Cross Index No. E-7 T. 35N R. 27W PMM

Sec. 5



• - corner this sheet