INSTRUCTIONS

1. Original and/or su[illegible]ent record used to evaluate the corner position.
2. Description of evid[illegible] found, note discrepancies in the record, state method of est[illegible]hing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 486 COR 6 / HES 485 COR 4 SEC 7
T36N R31W Lincoln Co.

FND OLD STONE MON W/ "X" CUT 0.70' ABOVE GRD & "6 HES---" WRITTEN ON SW SIDE
FND OLD BT 14" LODGEPOLE PINE STUMP N43°E 24.05' DIST ; NO BT SIGN
FND OLD BT 15" LODGEPOLE PINE STUMP N80°E 27.44' DIST ; NO BT SIGN

SET BT 8" SPRUCE N29°E 15.10' DIST SCRIBED "X BT"
SET BT 13" LODGEPOLE PINE N87°E 33.95' DIST SCRIBED "4 HES 485"
SET STEEL POSTS W/ DECALS 84-2 & 84-9
1) N20°E 1.65' DIST.
2) S70°E 0.90' DIST.

4

SKETCH OF CORNER

CERTIFICATION

I. _____ certify the information shown herein is true and correct.

Signature Ground Party Chief

I, Thomas E. Sands certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" 70-22-101, et seq., M.C.A.

Thomas E. Sands
Signature of Surveyor & Seal

Date: 7/23/93 Reg. No. 7975-S

Employer: Sands Surveying, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 27, 1993 day of 19 , was noted on the cross-index plat and is assigned page No. 5370, in book No. _____

Coral M. Cummings By DB
County Official

Sec.

• - corner this sheet

Cross Index No. HES486-6 T. 36N R. 31W PMM