**INSTRUCTIONS**

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

# CERTIFIED CORNER RECORDATION

Corner SE 1/16 SECTION 11 T. 37N R. 28W P.M.M. Lincoln County

(1) No previous record or evidence.

(2) Monument and accessories set to perpetuate corner position; Set a standard Forest Service 3¼ inch alum. cap on a 5/8 inch rod 28 inches into the ground; from which:

A 7 inch pine bears N 60 E 25.75 feet scribed SE 1/16 S11 BT

A 6 inch pine bears N 9 E 10.15 feet scribed SE 1/16 S11 BT

Set a U.S.D.A. steel post 3 feet north.

T37N R28W
SE 1/16 S11
WARREN 1989 27345

DECLINATION 19°




SKETCH OF CORNER

CERTIFICATION

I, DAN CROFT certify the information shown herein is true and correct.

Signature Ground Party Chief

I, H. GENE WARREN certify that this corner record correctly represents work performed by me or under my supervision in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

2734 S
Registered Land Surveyor & Seal

Date: 7-28-89 Reg. No. 27345

Employer: ROCKY MTN SURVEYORS

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the Sept 11, 1989 day of 19, was noted on the cross-index plat and is assigned page No. 4089, in book No. _____.

County Official Deputy

Sec. 11

11

• · corner this sheet

Cross Index No. H-20 T. 37N R. 28W PMM