LINCOLN COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
AFFIDAVIT OF WASTEWATER TREATMENT AND DISPOSAL SYSTEM COMPLIANCE REVIEW FOR SYSTEM INSTALLED, REPAIRED OR REPLACED WITHOUT A VALID PERMIT

Issue Date: 05/04/2022

2023

Property Owner: Bridger, Allan Darcy

Mailing Address: [redacted]

Telephone: [redacted]

Name of Person Who Installed System Being Reviewed: Dale Schmidt

Type of System Work Reviewed:

___ New Installation ____ Existing System

____ Repair ____ Replacement __XX__ Extension ____ Other

Describe: 1,000-gallon septic tank + 500 gallon pump chamber. Pressure-dosed system with standard absorption trenches, 1/8" orifices spaced @ 5-feet, ME40 pump. 3 laterals @ 36-feet in length each (3-ft wide pressure-dose trenches).

Property Description:

Legal: CARPENTER LAKE LOTS UNIT 2, S28, T37 N, R27 W, ACRES 0.628, NET ACRES 0.561 LOT 8 PM 3987

Address or Location: 171 Carpenter Ln, Eureka, MT 59917

Assessment Code: 0000011224

Reviewed Design Components:

Wastewater Flows: 300 gpd (3 bedroom) Sewer Lines: Schedule 40 PVS (4")

Septic Tank: 1,000-gallon + 500 gallon dosing Effluent Filter: Yes Dosing or Lift Tank: Yes

Drainfield: 108 Lineal Feet Drainfield Construction: drain rock Hydraulic Function: yes

Comments:

System Review Documentation Statement:

I, Nicholas Raines, have inspected/reviewed the components of this system as listed above and found it to be in compliance with the sizing, construction, orientation and operating requirements of Chapter 17, Subchapter 36 A.R.M., Circular DEQ-4 and Lincoln County Wastewater Regulation.


Signed: Nicholas J. Raines *Date:* 05/04/2022

Title: *Environmental Health Specialist*

NOTICE: This document is not a permit for installation, repair or alterations of a wastewater treatment system. It is merely a statement of affirmation that the Department has conducted an on-site review of an otherwise illegal system and found it to be in compliance with all applicable requirements for that system. This affidavit effectively removes the illegal installation status on this system.

DISCLAIMER

This affidavit of review is not a guarantee by the Department that the system will continue to function properly for any prescribed period of time.


Well
Carpenter Ln
10' off Northline
less than
10% slope
at drainfield
110'
100'
10' off westline
3-36' pressure dose lines
35'
13-36"
10' off eastline
2-3"
at relief
30' sch 40-1½"
filter
pump
1000-500 Tank
House
cleanout
sch 40-4"