I hereby certify that the survey shown hereon was conducted for the purpose of National Forest Management and in accordance with the policies CERTIFICATE OF SURVEY set forth in FMS 7152. **LEGEND** Forest Supervisor: DEPENDENT RESURVEY AND PARTIAL FOUND SECTION CORNER MONUMENT AS NOTED SUBDIVISION OF SECTION 12 FD. 3 1/4 INCH DIA. BLM BRASS CAP 1/4 CORNER FD. BLM BRASS CAP (1968) AS SECTION CORNER TWP 32N, R 34W, P.M.M. FOUND 1/4 CORNER MONUMENT AS NOTED LINCOLN COUNTY, MONTANA (S 89'43'00' E) (40.07 CH) (S 89°24'33' E) (2663.83) FOUND 2 1/2 INCH DIAMETER BRASS CAP STAMPED 2343-S (1975) FOR: CHAMPION REALTY INC. (FLORIDA) S 89*22'50" E 2664.68 APRIL 1994 FOUND 5/8 INCH DIAMETER REBAR GRAPHIC SCALE WITH A 1 1/4 INCH DIAMETER PLASTC CAP STAMPED 4661-S SET 3 1/4 INCH DIAMETER ALUMINUM MONUMENT ATTACHED TO A 5/8 INCH DIAMETER X 30 INCH LONG ALUMINUM (IN FEET) ROD STAMPED KED 4975-S (1994) 1 inch = 400 ft.N 76*54'04" E FOUND ORIGINAL HES STONE AS NOTED 0.91 PURPOSE OF SURVEY: The purpose of this survey is to retrace, set FOUND 3 1/4 INCH DIAMETER ALUMINUM MONUMENT PER COS NO.1083 CDS 1083 corners and mark the boundaries of an existing record parcel, distinguishing between Champion Realty Corporation (Florida) land and public lands pursuant to Section 76-3-401, M.C.A., as shown hereon. COMPUTED LOCATION PER RECORD BRUSHED, BLAZED, AND POSTED LINE PER U.S.F.S. SPECS FD. 3 1/4 INCH DIA. ALUMINUM CAP STAMPED SURVEY HISTORY: Original G.L.O. survey by Allen Benedict in 1903. BLAZED LINE PER COS NO. 1083 5612-S (1981) U.S.F.S. REFURBISHED THIS SURVEY Retracement of the North Half of the East line RECORD AS PER COS NO. 1083 HILLS-U.S.F.S. during the survey of HES 741 by E.R. Johnson in FD. HES 741 STONE CORNER #7 00*14′ RECORD PER HES 741 SURVEY MDL FD. 3 1/4 INCH DIA. ALUMINUM DISK ON A 5/8 INCH ALUMINUM ROD STAMPED Remonumentation by B.L.M. in 1967. RECORD AS PER COS NO.1287 JHN [] RECORD PER GLO Retracement of South line by J.T. Shaw in 1975 5612-5 (1982) as per Certificate of Survey No. 195. Retracement of the North Half of the East line by M. Lauteren in 1978 as per Certificate of Survey No. 535A. FD. 3 1/4 INCH DIA. BLM BRASS CAP (1967) FD. 3 1/4 INCH DIA. U.S.F.S. ALUMINUM FD. 3 1/4 INCH DIA. ALUMINUM CAP (1981) (2675.81) STAMPED 5612-S (U.S.F.S.) Section Breakdown by USFS (Hill) November 1982 (5330.40) Total 1/4 CORNER [N 89*50'47" W] [2654.57] as per Certificate of Survey No. 1083. 5328.93 Total CAP (1982) (S 89*50'47' E> (2654.58) (S 89'50'47' E) 1336.82 S 89*48'49' E 2673.65 Retracement of Certificate of Survey No. 1287 N 89*48'49" W 2655.28 1/4 (1337.91) \$ 12 × by Ninneman Engineering (West Half) as per 668.41 (668.95) 1327.64 668.41 (668.96) 11 12 1327.64 CE 1/16 1336.82 Certificate of Survey No. 1287. (1327.28) [1327.28] METHOD OF SURVEY: THEODOLITE-EDM TRAVERSE - Adjustment by STARNET FD. 3 1/4 INCH DIA. ALUMINUM MONUMENT (Least Square) STAMPED 5612-S (1982) U.S.F.S. BASIS OF BEARING: All bearings are based upon those bearings reported on Certificate of Survey No. 195 obtained from CDS 1083 668.25 668.25 appropriate ties thereto and Certificate of Survey S 89*50'47' E 1336.49 No. 1083 and Certificate of Survey No. 1287 reported to bear S 89°36'52" E. COS NO.1287 CH3 During the course of this survey we determined (40.00 (2661.0 2660.85 [2671.81 (2671.77 2670.07 39 the position of several USFS monuments and compared them to record positions. These positions were S 89*42'49' E 2664.00 generated from Certificate of Survey No. 1083. Some SW 1332.00 668.08 668.08 inconsistency was noted and reported to USFS. After (1331.38) (\$ 89*43'47" E) ⋧⋒⋒ careful analysis, the USFS decided to accept the 666.00 S 89*42'49' E 1336.16 1336.16 666.00 field locations and honor the true boundary lines 00*01'00* 00*35'34* 00*36'59* □ û > S 89*52'46' E 2672.31 as marked and posted previously. These variances 00°14′30° 00°14′30° 00°14′28° were also verified on Certificate of Survey No. 1287. 32N32N00*17*55* 1333.49 SEE DETAIL "B" SEE DETAIL 'A' 1/64 [666.70] [666.71] 667.09 zζ \$ 89*39'50' E 1334.18 > [1333.41] 00°25′4 00.16.11 1/64 z z APPROVED: Chairman, Lincoln County, Montana Commissioners CDS ND.1287 FD. 3 1/4 INCH BRASS CAP STATE OF MONTANA (1975) STAMPED 2343-S COUNTY OF LINCOLN, 1/4 1335.49 1335.49 FD. 3 1/4 INCH DIA. BLM BRASS CAP (1968) [667.73] BASIS OF BEARING [1335.45] [667.72] 13 13 \$ 89*36'52' E (\$ 89*36'52' E) [\$ 89*36'52' E] (\$ 89*58'00' E) 2670.99 FD. 3 1/4 INCH DIA. \$ 89°56'44" E 2672.71 (2670.89) BRASS D1SK (1975) SEE DETAIL 'C' (\$89*56'22' E) (2675.92) STAMPED 2343-S [2670.90] (Z 89*58'00' E) (40.04 CH) {40.04 CH}

DAVIS SURVEYING INC.

TROY, MONTANA (406)295-5441

FOREST SUPERVISOR'S CERTIFICATE: