## **CERTIFICATE OF SURVEY:**


### PARTIAL RETRACEMENT

**IRREGULAR PLAT NO. 681** 

In the NW 1/4 of Section 12 Twp. 31 N., R. 34 W., P.M.M.

For: William & Shelly Warrick & Lloyd Dean Nelson

Date: October 2015



c.o.s. 25

# **LEGEND**

- SET A 5/8 INCH DIA. REBAR WITH A 1 1/4 INCH PLASTIC CAP STAMPED K.E.D. 4975-S
- FOUND A 5/8 INCH DIA. REBAR CAPPED K.E.D. 4975-S
- FOUND 1 1/4 INCH STEEL ROD
- FOUND 3/4 INCH DIA. PIPE
- FOUND 3" R/R SPIKE
- **COMPUTED POINT**
- RECORD PER C.O.S. 128
- RECORD PER IRREGULAR PLAT NO. 358
- RECORD PER IRREGULAR PLAT NO. 243
- RECORD PER IRREGULAR PLAT
- NO. 681
- RECORD PER C.O.S. 1833


#### PURPOSE OF SURVEY

The purpose of this survey is to partially retrace the south boundary of Tract 5-17C and the south boundary of Irregular Plat No. 681, and no new parcels have been created; therefore, this survey is exempt from review as a subdivision being completed pursuant to 76-3-404 M.C.A.

#### CERTIFICATE OF SURVEYOR

STATE OF MONTANA County of Lincoln

I, Kenneth E. Davis, a registered land surveyor do hereby certify that I have performed the survey shown on the attached plat or that such survey was performed my servision to my best knowledge and ability; that said survey is the monuments found and set occupy




#### CERTIFICATION OF LINCOLN COUNTY EXAMINING LAND SURVEYOR:

Examined this 12 day of October 2015 A.D. Ronald A. Pearson Professional Land Surveyor No. 9008LS

STATE OF MONTANA COUNTY OF LINCOLN

Filed on this day of October 2015 A.D. at 10:00



[\$68'15'00"W] [125.0'] \$68'17'13"W 124.97'

IRREGULAR PLAT

[N68.15,00,E]

N68°17'23"E 124.97 [N68'15'00"E] [125.0']

10.00' S68° 17' 13"W 681 10.00' RREGULAR PLAT NO. 681 [10.0'] RREGULAR PLAT NO. 681

\ [N21°45'00"W]\ \_\_N21°45'00"W

10.00' [10.0']

C.O.S. NO. 4394

TRACT 5-17C

S68°17'13"W 13.65

۸9

50

50'

N66°10'15"E 14.97 1156670'40"W}