- uncies in the record, state method of establishing
- 3. Description of m
- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and scaled by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED	CORNER	RECOI	RDATION
-----------	--------	-------	---------

26 N R. 27 W P.M.M. LINCOLN Corner NW /16 ORIGINAL AND/OR SUBSEQUENT RECORD None


EVIDENCE FOUND

Set 12" Alum. Cap on 5/8" Rebar. Established two RM's PERPETUATION A 8" D. Fir bears N70°W, 3.6 Feet, an 8" D. Fir bears 517°W, 10.5 Feet. Tagged both RM Trees with a MARLS Land Monument Sign

Note: Declination used 20° E

book No. .

Measurments taken to center of tree.



T. <u>26N</u> R. <u>27W</u> PMM

corner this sheet