	$1/4 - \frac{2}{11}$ - 26 N - 29 W LINCOLN
Со	er
i.	903 Subdivision of T27N. R29W by Charles H. Albee & William K. Trippet: Set a sandstone, 14x10x5 ns., 10 ins. in the ground and 2 bearing trees.
	964 BLM Remonumentation by Richard L. Larimer & Harold W. Grusing: Found original stone firmly set and replaces stone with a iron post, 30 ins. long, 2 1/2 ins. diam., 24 ins. in the ground with crass cap. Found SE bearing tree and stump of NW bearing tree. Establishes 1 new bearing tree.
	N fir, 12 ins. diam., bears N64E, 12 lks. dist., mkd. 1/4 S2 BT. 981—1984 C.O.S.'s 935, 975, 1019 & 1267 by Albert Putnam. Mt. Reg. No. 4375S: Found BLM Brass ap.
	985 Certified Corner Recordation by Charles Doyle, MT Reg. No. 2516S: Finds the BLM monument. inds 2 bearing trees:
	A burnt lodgepole pine, 11 ins. diam., bears N64°E, 12 lks dist. A burnt lodgepole pine, 11 ins. diam., bears S68°E, 8.9 ft. dist.
	ulso refers to C.O.S. #1400.
	NOTE: C.O.S. #1400 refers to section 10 and makes no mention of the 1/4 cor. for secs. 2 and 11)
II.	ound: A 2 1/2 in diam. iron pipe, firmly set in a collar of stone, with 3 1/4 in. diam. BLM brass ap mkd. as shown below, from which:
	A burnt down fir, 12 ins. diam., bears N64E, 7.9 ft. dist., mkd. with visible scribe marks. (BLM)
III.	stablish 2 new bearing trees:
	A Ponderosa pine, 5 ins. diam., bears S48°W, 31.6 ft. dist., mkd. 1/4 S11 BT. A Ponderosa pine, 4 ins. diam., bears N18°W, 36.5 ft. dist., mkd. 1/4 S2 BT.
	ainted the scribed faces red and 6 in. wide red bands around the bearing trees. Attached Land urvey Monument and Bearing Tree signs. This corner located in the burned area of the 1984 oughton Creek fire and was extensively logged after the fire. Only a very few small trees were vailable for bearing trees at this time.
	LAT 48°01'55.96323"N LONG 115"18'03.10175"W NAD 83 ate of Fieldwork: 7/20/2011 urvey crew: Tom Hommel agnetic declination: 20° East assumed quipment used: Hand compass and loggers tape
	S. Forest Service, Supervisors Office, 31374 Hwy. 2, Libby, MT 59923 (406) 293-6211
	Thomas Marchines, 12" burnt down fir 12" burnt down fir MARCHINE BURKHART TY DESTRUCTION OF THE CONTROL OF TH
-	NOT TO SCALE Employer:
Offic	of Clerk and Recorder, County of Lincoln 237363 BOOK: CCR CCER'S PAGE: 11948 Pages: 1 STATE OF MONTANA LINCOLN COUNTY RECORDED: 02/22/2012 9:25 KOI: CCER'S TAMMY D. LAUER CLERK AND RECORDER FEE: \$0.00 By Carrier Stensy To: FILED , Cross Index No. E 19 T. 26N. R. 29W. P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

• corner this sheet