## INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**


\_P.M.M. Lincoln R. \_ 29W. C-E-NW-NE 1/256 Sec. 22 T. 26N County

Set 5/8" X 24" capped steel pin stamped JHN 4661S

Set 10" Larch bearing tree scribed C-E-NW-NE 1/256 BT from which the corner bears s 89°W 21.8 ft.

Set 8" Larch bearing tree scribed C-E-NW-NE 1/256 BT from which the corner bears S 17 E  $\,$  5.4 ft

Set a location poster on 3" Larch from which the corner bears N 32°W 3.1 ft.



22

deputy

· corner this sheet

T. 26N R. 29W PMM

book No.