4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

G.L.O. RECORD: SET 14x 10x5" LIMESTONE 4 NOTCHES ONE, & 2 NOTCHES ONW. A 6" PINE BEARS N27°5'E 32 LKS. A 6" PINE BEARS \$30°45E 18 LKS. A 26" PINE BEARS SIZO W 85 LKS. A 5" PINE BEARS N 50° W 8 LKS.

FOUND; A MOUND OF STONE WITH PART OF ORIGANAL STONE, A FEW NOTCHES VISIBLE

SET 5/8' XZ4" RERAR WITH	(3) (8) (8) (8) (8) (8) (8) (8) (8) (8) (8
PLASTIC SURV. CAP 79755	7 327.

**SKETCH OF CORNER** 

Thomas E. Sands Date: 11/24/93 Reg. No. <u> 7975-S</u> Sands Surveying,

Office of Clerk and Recorder, County of AMCoh . This "corner Dec 3,1923 record" was filed for record on the \_\_\_ \_ day of 19 , was noted on the cross-index plat and is assigned page No. book No.

County Official

· corner this sheet

T. 26N R. 29W PMM Cross Index No.