## INSTRUCTIONS

it record used to evaluate the corner p usition

2. Description of evidence found, note discrepancies in the record, state niethod of establishing lost or obliterated

corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

P.M.M.\_Lincoln CornerSouth & corner Section 34 30W. .County

1. 40 chains: Set an iron post 3 ft. long, 1 inch in diameter, 24 inces in the ground, for 1 Section corner for Section 34 only, with brass cap marked.

from which a Fir 8 inches diameter bears N 1°E 69 links distance, marked 4 S 34 B.T. There being no other tree available, I raise a mound of stone, 2 feet base 11 feet high North of corner.

- 2. Found: 1916 brass cap monument as shown below.
- 3. Painted monument and accessories with bright red paint.



Found 2" BC monument marked as shown

