## INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.

  3. Description of monument and accessories set to perpetuate the corner position.

  4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

NW-SE-SE 1/256 Corner Sec.34 T. 26N Lincoln P.M.M. County

- 1. This corner not previously set.
- 2. Set: A 3" X 30" aluminum capped monument marked as shown below from which, A 10" Pine bears S  $44^{\circ}E$  14.7 feet scribed NW-SE-SE 1/256 S34B.T. and posted. A 7" Larch bears N  $09^{\circ}$ E 18.9 feet scribed NW-SE-SE 1/256 S34B.T. and posted. A location poster on a 4" Spruce bears N  $48^{\circ}$ W 6.2 feet. Painted monument and accessories with bright red paint.



Set 3" aluminum monument marked as shown.

LOCATION POSTER 6.30 SET AN ALUMINUM IN A 4"SPROKE WHICH EARS N 48 W G.Z.H.  NARKED AS SHOWN.  SKETCH OF CORNER  10" PINE BT.	CERTIFICATION  1. David Stanley certify the information shown herein is true and correct.  Signature Country Chief  1. Jack H. Ninneman certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)  Signature of Surveyor & Scal  Date: Aug. 82 <sub>Reg. No.</sub> 4661S  Ninneman Engineering Inc. Employer:
Office of Clerk and Recorder, County of Lincol  record" was filed for record on the Supt 10  was noted on the cross-index plat and is assigned page No.  book No.  Eleanort Vaugher by County Office  Cross Index No. 12-16,17	cial deputy