INSTRUCTIONS

- 3. Description of monument and accessories set to perpetuate the corner position.
- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Olagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner _	SW 1/6	Sec.	_33	 T. <u>27 N</u>	R.	27 W	P.M.M	LINCOLN	 County

ORIGINAL AND/OR SUBSEQUENT RECORD None

EVIDENCE FOUND None

PERPETUATION Set 11/2" Alum. Cap on 5/8" Rebar. Established Two RM Trees. An 36" Larch stump bears N87°E, 3.7'. A 7"LP Pine bears N25°E, 7.6 . Both RM's Blazed and Tagged with MARLS Land Monument Sign.

Note: Declination used - 20° E Measurements taken to center of tree.



Cross Index No. Y-10 T. 27 N R. 27 W PMM