					•	
•	1/4 35					
Corne	er _					INCOLN County
l. <u>13</u> lir	<u>902 North & South</u> mestone, 20x12x8	<u>boundaries of T2</u> ins., 15 ins. in the	7N. R29W by Bu ground and 2 I	<u>rton S. Adam</u> bearing trees.	s & William	<u>C. Weeks:</u> Set a
a	iron post, 30 ins.	long, 2 1/2 ins. (diam., 24 ins. in	the around v	vith brass o	nd replaces stone wit ap marked as shown new bearing trees.
15 C	981-1984 C.O.S.'s ap.	935. 975. 1019 &	1267 by Albert	Putnam. Mt. I	Reg. No. 43	75S: Found BLM Bras
st oı fil	nown below. Finds ne of the BLM bea	the original GLO do ring trees in the S he area. Unable	ead fir bearing t SE quadrant. No to set new bearl	ree in the NE o evidence of na trees due	quadrant of the NW BLA to the rece	the BLM monument of Ind a saw stump for I bearing tree due to Int Houghton Creek
j. Fo	ound, a 2 1/2" dia round, marked as s	m. iron pipe, firml shown below, from	y set with a 3 ' which:	1/4 in. diam.	BLM brass	cap, 3 ins. above
	A saw stump, '	wn Douglas fir, 11 18 ins. diam., 1 ft d post with Survey	. high, bears S40	5°E, 21.0 ft. c	ft. dist., rot list., with n	ted face. o visible marks.
II. Es	Establish 2 new bearing tree:					
	A Douglas fir, 6 ins. diam., bears N57E, 33.0 ft. dist., mkd. 1/4 S35 BT. A pine, 8 ins. diam., bears S7E, 29.4 ft. dist., mkd. 1/4 S2 BT.					
Pe Su	ainted the scribed urvey Monument an	faces red and 6 ii d Bearing Tree sig	n. wide red band Ins.	s around the	bearing tre	es. Attached Land
St Mo	ate of Fieldwork: 4 urvey crew: Tom Ho agnetic declination: quipment used: Har	LON NAD - /27/2011 ommel 20° East assume	d			217 MR 2 9 M OR 3 2 9
U.	S. Forest Service,	Supervisors Office,	31374 Hwy. 2,	Libby, MT 599	23 (406) 2	93-6211
	11" D. fir (dead & down)		D. fir	certify to the Control of the Contro	Ignot Market Bur	TIFICATION DEPTH 10800LS DEPHH 10800LS DEPTH 108
		1 !-		Employer		
Office (F	, obtainey or	CINCOLN COUNTY 012 9:02 KOI:		Pages: 1	Sec. 35

FEE: \$0.00 TO: FILED ,

Cross Index No. Z 19 T. 27N. R. 29W. P.M., MT

• corner this sheet

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors