

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

Corner E $\frac{1}{4}$ S36 T. 27N R. 29W P.M.M. Lincoln County

-

NW Cor 531
T27N R28W

N6°03'25" W 361.56

E 1/4 536
T27N R29W

N6°19'39" W 2635.74

S54°20' W 301.56

large burned stump
(No Blaze)

Burned, standing trees
blazed and painted red
for roughly N-S line

SE Cor 536
T27N R29W

MONTANA
DWIGHT
AXEL
0846
REGISTERED
LAND SURVEYOR



1. Steven B. Ivey, 9329LS
certify the information shown herein is true and correct.

Steven B. Ivey
Signature Ground Party Chief

1. Dwight L. Axelsen

certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)


Dwight L. Peterson
Signature of Surveyor & Seal

Date: Nov. 89 Reg. No. 8641LS

Employer: Delta Engineering

Office of Clerk and Recorder, County of Lincoln. This "corner
record" was filed for record on the Dec 1 day of 1989
was noted on the cross-index plat and is assigned page No. 4115, in
book No. Grant of Supt by Bill Smith

Cross Index No. _____ T. _____ R. _____ PMM

Sec. 36 E $\frac{1}{4}$ 

- - corner this sheet