

INSTRUCTIONS

1. Original and/or substitute record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state missing corners.
3. Description of monument and accessories to perpetuate corner position.
4. Sketch of corner, show all pertinent details which can be shown in a sketch example, corner marking, topography ties, position of accessories.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.


CERTIFIED CORNER RECORDATION

Corner C 1/4 SECTION 2 T. 27N R. 30W P.M.M. LINCOLN County

1) NO CORNER ESTABLISHED BY G.L.O.

2) NONE FOUND

3) FOR CORRECT CORNER POSITION - SET 5/8" x 24" REBAR WITH ORANGE CAP STAMPED "GOACHER 7318-S" FROM WHICH BEARS:  
 AN 8" FIR N. 30° W. 15.3'  
 A 16" LARCH S. 80° W. 6.0'  
 BEARING TREES HAVE SNOW BLAZE & FOOT BLAZE WITH "RM" SCRIBED INTO FOOT BLAZE. BT TAGS ARE ATTACHED TO BOTH TREES SET 2" x 2" x 30" RED & WHITE GUARD STAKE



SKETCH OF CORNER

CERTIFICATION

I, RICHARD G. GOACHER  
 certify the information shown herein is true and correct.

Signature Ground Party Chief

I, RICHARD G. GOACHER  
 certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (MCA, 1973, 82-1001, et seq., M.C.A.)


Signature of Surveyor & Seal

Date: 11-91 Reg. No. 7318-S

Employer: SELF

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on Nov 20, 1991 was noted on the cross-index plat and is assigned page No. 4589, in book No. \_\_\_\_\_

Coral Cummings by Bill Bushell  
 County Official



• corner this sheet