

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.


CERTIFIED CORNER RECORDATION

Corner C-W 1/16 T. 28N R. 29W P.M.M. Lincoln County

(Record) No previous record)
(Found) No evidence

(Set) Set a 5/8" x30" alum. rod with 3" diam alum. cap. Marked new BTs as follows:

Fir 5" diam. bears N54°W 12.1' scribed CW 1/16 S15BT
L. Pine 9" diam. bears N46°E 15.7' scribed CW 1/16 S15BT



SKETCH OF CORNER

CERTIFICATION

1. Dan Croft

certify the information shown herein is true and correct.

Signature of County Clerk

H. Gene Warren

I, H. Gene Warren, certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-01, et seq., M.D.A.).

H. Gene Warren
Signature of Surveyor & Seal


Date: 6/5/87 Reg. No. 142734

Employer: Rocky Mountain Surveyors

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 1 day of 1987 was noted on the cross-index plat and is assigned page No. 3581, in book No. _____

Cross Index No. L-14 T. 28N R. 29W P.M.M.

Sec. 15



• corner this sheet