
CERTIFIED CORNER RECORDATION

Corner N-S 1/64 Sec.s 34 & 35 T. 28 N. R. 30 W. P.M.M. LINCOLN County

- I. Record: No previous survey.
- II. Found: No evidence found.
- III. At the corner point
 Set an iron rebar, 24 ins. long, 5/8 ins. diam., 40 ins. in the ground, with a 3 1/4 ins. diam., aluminum U.S.F.S cap mkd. as shown:



From which:

An iron rebar, 24 ins. long, 5/8 ins. diam., 22 ins. in the ground, for a reference monument, bears S38°54'36"W, 91.15 ft. dist., with a 3 1/4 ins. diam., aluminun U.S.D.A. cap mkd. RM 2. An iron rebar, 24 ins. long, 5/8 ins. diam., 22 ins. in the ground, for a reference monument, bears S81°09'53"W, 88.77 ft. dist., with a 3 1/4 ins. diam., aluminum U.S.D.A. cap mkd. RM 1.

NOTE: As this corner falls in a hay field there were no trees within limits for bearing trees.

Survey crew: Steve Boyer, Tom Hommel

Magnetic declination: 20° East assumed


Equipment used: Hand compass and loggers tape

ROGER O.
GREEN
13769LS

10 SURVE
1923 (406) SURVE

MONTANA

U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923 (406)



CERTIFICATION

Steven A. Boyer 9750LS

certify the information shown herein is true and correct.

Signature Ground Party Chief

Roger O. Green

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70.20-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date:1/24/2001 Reg. No. 13769LS

Employer: U. S. Forest Service

Sec. 34

corner this sheet

Cross Index No. X.5—17 T. 28N. R. 30W. P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors