- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners,
- Description of monoment and accessories set to perpensage the corner position.


 Skeftch or coiner, show all perturent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.,
- Certification must be signed and scaled by Registered Land Surveyor in State of Montana.
- Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

SEZ - PSZ - 41/1 U renro **29N** 270 P.M.M. Lincoln County

- No Original Record.
- N/A 2.
- I set a 28" long 2-1/2" diam. aluminum pipe with 3-1/4" cap marked as shown below, from which a 7 ins. diam. Doug Fir bears N13°W, 59.40 feet з. dist- marked W1/16 S29 BT, and a 14 ins. diam. Doug Fir bears S77°W, 16.75 feet dist. marked W 1/16 S32 BT.

BTs tagged, corner posted, rock mound and BTs painted red per contract requirements.



SKETCH OF CORNER

Office of Clerk and Recorder, County of Lincoln. This "corner record"	Sec.	32			
was filed for record on the 10th day of 10v. 19 81, was noted on the cross-index plat and		t I	1	i i]
is assigned page No. 1363, in book No. / Eleanor L. Vaugho by Betty		j)/ 	1
County Official & Conces	∤	! !		<u></u>	
Cross Index No D. 29N R. 29W PMM	} - `	- · -	 		

• - corner this sheet