

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state missing or obliterated corners.
3. Description of monument and accessories to perpetuate corner position.
4. Sketch of corner, show all pertinent details which can be shown in a sketch example, corner marking, topography ties, position of accessories.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner NW 1/16 Sec. 3 T. 29 N R. 31 W P.M.M. Lincoln County

1. No original corner established
2. Not found
3. Set a 3/4" x 30" aluminum rod with a 3/4" aluminum cap, 25" in the ground for corner location. Established the following references to the corner:



A fir, 12 ins. diam., bears N.20°W. 40.3 lks. (26.6 ft.) dist. marked NW1/16 S 3 BT

A fir, 9 ins. diam., bears S.80°W. 22.9 lks. (15.1 ft.) dist. marked NW 1/16 S 3 BT

Set a steel guard post w/ survey marker decal attached

Attached bearing tree tags and land survey monument signs to each bearing tree.

Cap of monument stamped as follows:



SKETCH OF CORNER

CERTIFICATION

I, RICHARD G. GOACHER
 certify the information shown herein is true and correct.

Signature Ground Party Chief

I, Richard G. Goacher
 certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (78-21-101, 102, 103, M.C.A.)

Signature of Surveyor & Seal

Date: 6-87 Reg. No. 7318-S

Employer: Goacher & Assoc.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on July 8, 1987 was noted on the cross-index plat and is assigned page No. 3607, in book No. _____

Janet B. Sweeney
 County Official Deputy

