1. Original and/o 2. Description of e corners.

- Description of monument and accessories set to perpetuate the corner position.
   Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
  6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

N W 1/16 th. Sec. 19 T. 30 N., R. 33 W., P.M.M. Lincoln

Set 5/8" x 18" steel rebar with yellow P.V.C. cap stamped KED 4975 S for NW 1/16 corner. From which I scribed and marked two new bearing

- A larch 7 inches in dia. bears N 87° 30' E 56.4 feet in 1) distance, scribed NW 1/16 S 190Bt.
- A lodgepole pine 7 inches in dia. bears N 0° 30' W, 27.2 feet in distance, scribed NW 1/16 S 19 Bt.

Painted the face scribe and red bands around each bearing tree and attached a bearing tree sign on each.

