INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancles in the record, state method of establishing lost or obliterated.
- Description of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.


 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

N 1/16 of Secs. 11 & 12 30 N., Lincoln Corner P.M.M. County

- No records found at Lincoln County Courthouse.
- II. No evidence on the ground.
- III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 24 ins. in the ground with attached 3 1/4 ins. dia. U.S.D.A. Forest Service aluminum cap, marked as shown:



from which

A douglas fir, 12 ins. dia., bears S61 $^{\circ}$ E, 14.6 ft. dist., mkd. N 1/16 S12 BT. A douglas fir, 9 ins. dia., bears S50 $^{\circ}$ W, 7.0 ft. dist., mkd. N 1/16 S11 BT.

Painted a red band around each bearing tree and attached "Land Survey Monument" & "Bearing Tree" signs.

Raise a collar of stone around aluminum rod.

Magnetic Declination: East, 20

SKETCH OF CORNER

mste ''∵orner Office of Clerk and Recorder, County of record" was filed for record on ___

was noted on the cross-index plat and is assigned page No.

book No. _

County Official.

Cross Index No. .

CERTIFICATION

certify the information hown herein is true and correct.

Alvah F. Hughes certify that this Corner Record correctly represent

11/12/91

U.S. FOREST SERVICE

corner this sheet