## INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
   Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.

  3. Description of monument and accessories set to perpetuate the corner position.

  4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

C-E-NW 1/64 Sec. 12 Lincoln P.M.M. Corner \_ County

- No record found at Lincoln County Courthouse
- II. No evidence on the ground
- III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod. 30 ins. long, 27 ins. in the ground with attached 3 1/4 ins. dia. U.S.D.A. Forest Service aluminum cap, marked as shown:




from which

A douglas fir, 22 ins. dia., bears N44  $^{\circ}$ E, 16.5 ft. dist., mkd. C-E-NW 1/64 S12 BT. A douglas fir, 19 ins. dia., bears N61  $^{\circ}$ W, 20.3 ft. dist., mkd. C-E-NW 1/64 S12 BT.

Set a 6 ft. galvanized steel guard post with "Survey Marker" and "Property Boundary" decals attached,

Painted a red band around each bearing tree and attached "Land Survey Monument" and "Bearing Tree"

Magnetic Declination: East, 20



Office of Clerk and Recorder, County of _	Lincoln	This "corner	Sec. 12
record" was filed for record on	4-22-92:		
was noted on the cross-index plat and is a	ssigned page No	5057 in	<b> </b>
book No.	County Uti	ficial	
· Cr	F22.5	30 N 34 W	• - corner this sheet