- quent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ites, position of accessories, etc.


 5. Certification must be signed and scaled by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

W 1/16 of Secs. 1 & 12 30 N., Lincoln Corner . P.M.M. County

- No records found at Lincoln County Courthouse.
- No found evidence on the ground.
- III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 20 ins. in the ground with attached 3 1/4 ins. dia. U.S.D.A. Forest Service aluminum cap, marked as shown:




from which

A fir, 12 ins. dia., bears N53 $^{\circ}$ W, 16.9 ft. dist., mkd. W 1/16 S1 BT. A fir. 13 ins. dia., bears $N14^{\circ}E$, 36.8 ft. dist., mkd. W 1/16 S1 BT.

Set a 6 ft. galvanized steel guard post with "Survey Marker" and "Property Boundary" decais attached, 3 ft., West.

Painted a red band around each bearing tree and attached "Land Survey Monument" & "Bearing Tree"

Magnetic Declination: "East, 20°



Kenneth Kern

certify the information shown herein is true and correct.

Alvah F. Hughes

certify that this Corner Record correctly represents

11/13/91 7322LS

Reg. No. _

U.S. FOREST SERVICE Employer:

Date:

__ R. _

SKETCH OF CORNER

Office of Clerk and Recorder, County of . This "corner record" was filed for record on _____ was noted on the cross-index plat and is assigned page No. book No. E22 30 N 🗸

Cross Index No.

corner this sheet