INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.


 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

C-W-NE-SW 1/256 \$1 P.M.M. Corner_ County No record found at Lincoln County Courthouse.

II. No evidence on the ground.

III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 27 ins. in the ground with attached $3\ 1/4$ ins. dia. U.S.D.A. Forest Service aluminum cap



from which

A cedar, 6 ins. dia., bears S33 $^{\circ}$ E, 11.3 ft. dist., mkd. C-W-NE-SW 1/256 S 1 BT. A birch, 7 ins. dia., bears S36 $^{\circ}$ W, 12.7 ft. dist., mkd. X BT.

Painted a red band around each bearing tree and attached "Land Survey Monument" and "Bearing Tree" signs.

Magnetic Declination: East, 20

CERTIFICATION Hughes certify that this Corner Record correctly represent 7 Birch U.S. FOREST SERVICE Employer: ___ **SKETCH OF CORNER** Sec This "corner Office of Clerk and Recorder, County of record" was filed for record on _ was noted on the cross-index plat and is assigned page No umm book No. _

Cross Index No.

C .5-22.25

County Official

30 N

· corner this sheet