Description of evidence found, note discrepancies in the record, state method of establishing lostfor obliterated

- corners.

  3. Description of monument and accessories set to perpetuate the corner position.

  4. Sketch or corner, show all pertinent data which can best be shown in a sketch example; corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

P.M.M. Lincoln Corner Center North 1/16th. corner

- 1. This corner not previously set.
- 2. Set a U.S.F.S. aluminum monument 3" in diameter 30" long, stamped as shown in sketch below, from which a 6" Pine bears S83 E 15.0 feet scribed CN1/16S1 B.T. A 12" Fir bears \$43°W 30.5 feet scribed CN1/16 S1B.T. and A location poster attached to a 6" Pine bears S48°E 11.6 feet lines posted. blazed and painted run South and East from this corner.

SET AN ALUMINUM  MONUMENT  3"X30" MARKED  AS SHOWN.  SA30,5PT.  SA30,5PT.  SA30,5PT.  LOCATION  POSTER ON  A 6"PINE.	certify the information shown herein is true and correct.  Signature Ground Perfy Chief  I. Jack H. Binneman certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)  Signature of Surveyor & Sea!  Date: 1/12/82 Reg. No. 4661S  Employer: Ninneman Engineering Inc.
Office of Clerk and Recorder, County of Lincoln record" was filed for record on the January 18th was noted on the cross-index plat and is assigned page No. 148 book No	Sec. 1  day of 192;

CERTIFICATION