INSTRUCTIONS

Original and/or subtraction trecord used to evaluate the corner position

2. Description of evidence round, note discrepancies in the record, state method of establishment lost or obliterates corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all perlinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.


6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner <u>Cw 1/16 Corner Section 1</u> T. <u>31N</u> R. <u>29W</u> P.M.M. <u>Lincoln</u> Cou	orner _	_CW 1/16 Corner Se	ection 1	T	31N	R	29W	P.M.M.	Lincoln	Cour
--	---------	--------------------	----------	---	-----	---	-----	--------	---------	------

1. Corner was not previously set.

2. Set a 3" diameter aluminum monument, 30 inches long, from which, A 6" Fir bears N 54° W 22.0 feet scribed CW 1/16 S1 B.T. and posted. A 12" Fir bears S32°E 18.5 feet scribed CW 1/16 S1 B.T. and posted. A location poster attached to a 3" Fir bears S60°E 9.3 feet. Lines blazed and painted North and East from monument.



31N R. 29W PMM

· - corner this sheet