INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 1 Cor. Sec. 32 & 33 T. 31N R. 30W P.M.M. Lincoln

Original GLO Notes: Set a porphory stone 20x12x9 in., 15" in ground for ½ sec. cor. marked ½ on W. face from which:

A fir 16" bears N70 45'E 59 lks., mkd. ½ S33 BT.

A pine 30" bears S41 W 7 lks., mkd. ½ S32 BT.

(1898 by Paul S.A. Bickel)

Corner monumentation survey: The corner of sec. 28, 29, 32, & 33, as determined from the remains of the original bearing trees. At the corner point, set an iron post, 30" long, $2\frac{1}{2}$ " in diam., 27" in the ground, with brass cap mkd. T31N R30W

S29 S32 S33 1964

from which

The remains of the original bearing trees:

A larch 24" bears N28°E 95 lks., visible marks T31N R30W.

(Record N59°10'E)

A pine 18" bears S43½°E 82 lks., blaze overgrown.

A decayed stump bears S7°W 97 lks., no marks visible.

A larch 18" bears N78°W 26 lks., visible marks R30W S29.

The new bearing tree:

A fir 9" bears S130W_28 lks., Mkd. T31N R30W S32 BT. (1964 by Gerald F. Pittman, Cadastral Surveyor)

Found a BLM 32" brass cap on 2" iron pipe mon. w/ stones piled around mon.

MKD: T31N R30W

|S33 1964

Found Bearing Trees:

A 10" fir N38 E 24.5 feet, Scribing not visible.

A fallen BT(Original) N64 E 30.0 feet.

A snag(Original) S30 W 4.7 feet. Scribing visible. \$\frac{1}{4}\$ S32 11 A 13" fir N41 W 48.0 feet, scribing not visible.

All BT's painted and signed as per USFS Specs. and post w/ signs set near corner. Built rock cairn around corner 3' diam.

diam. & cleared ground to 6' diam.

Decl. 20°E Assumed.

Cor. MKD:

R30W T31N

S33 1964



CERTIFICATION Gennis Diffinabilit certify the information shown herein is true and correct. Signature Ground Party Chief Robert E. Findorff work performed ertily that this Corner Record corre Dale 1/11/87 Reg. No. 397

Employer: Self

SKETCH OF CORNER (SEE ABOVE)

Office of Clerk and Recorder, County of This "corner	1 1	
record" was filed for record on Nov 16, 1987		
was noted on the cross-index plat and is assigned page No. 3695, in		
book No fant by Sugal by Sul Swell _	++-	-

Cross Index No. X-9 T. 31N R. 30W PMM Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet