INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner S 1/16 Cor. Sec. 33 & 34 T. 31N R. 30W P.M.M. Lincoln

No original corner set by GLO.

3976ES


Set a $\frac{3}{4}$ " USFS Aluminum driveable monument 30" long, 21" deep w/ $3\frac{1}{4}$ " alum. cap Mkd: S 1/16 Corner falls on NW slope approx. 50' N. of old logging road & approx. 80' S. of old logging road. S33 | S34 1987

A 6" fir bears S82°E 25.0 feet, mkd. S1/16 S34 BT. Bearing trees: A 7" fir bears S55°W 11.0 feet, mkd. S1/16 S33 BT.

Built a rock cairn 3' diam around mon. and cleared to 6' diam. Set a sign post near cor. Painted and signed all bearing trees as per USFS specs.

Decl. 20°E (assumed).

Cor. mkd.: S1/16 S33 | S34 1987 3976ES



CERTIFICATION Denni#D#Findoff certify the information shown herein is true and correct. Signature Ground Party Chief Robert E. Findorff certify that this Corner Record correctly Dale 1/11/87 Reg. No. 3976E Employer: Self

SKETCH OF CORNER (SEE ABOVE)

Office of Clerk and Recorder, County of Lincoh This "corner	Sec.3	3,T3	31N.	R30)W
record" was filed for record on Nov. 16, 1987	-+				
was noted on the cross-index plat and is assigned page No. 3698, in		+	+		
book No Sant & Sugelly Duf Sixely County Official Description		- 🕂	- +		•
County Chicai 2542 4	1	i		- 1	

T. 31N R. 30W PMM <u>Y-13</u> Cross Index No. . Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors