

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found the east 1/4 corner of section 25 T31N R31W. Had no G.L.O. notes for the west 1/4 corner of section 30 and found no indication of the corner. Reset the corner by proportional measurement between the double section corners to the north and the south.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: June '70

Set Corps of Engineers brass cap (see sketch on reverse side)

1) 15" ponderosa pine bearing N29 1/2° E, 81 lks., marked 1/4 S30 BT


1) 12" power pole bearing S15 1/2° E, 155 lks., marked 1/4 S30 BP

Corner falls at the edge of the upper power line road.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See reverse side

Surveyor's Seal



I, James R. Staples
certify that the information shown herein is true and correct.


James R. Staples
Signature of Ground Party Chief

I, JOHN C. ERICKSON
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

John C. Erickson
Signature of Surveyor

3979 S
Registration Number

DIAGRAM OF CORNER:
T31N R30W



= Corner recorded on the sheet

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 28 day of Mar 1989, was noted on the cross-index plat and is assigned page No. 4023, in book No. 11

Janet E. Sigel by Bill Sigel
County Official

