## CERTIFIED CORNER RECORDATION


Corner SW-SE-SE 1/256 S19 T 31 N. R. 31 W. P.M.M. LINCOLN County

- 1979 Certificate of Survey No. 665 by J. H. Ninneman, MT Reg. No. 4661S: Set a 5/8" diam. steel rod with yellow cap stamped J.H.N. 4661S.
- Found a 5/8" diam. rebar with broken yellow plastic cap marked J.H.N 4661S lying alongside.
- III. At the position determined by survey, set a 5/8" diam. by 24" long rebar, flush with the ground, with 3 1/4" diam, aluminum cap marked as shown, from which the new bearing tree:

A fir, 10 ins. diam, bears S4'W, 9.8 ft. dist., marked SWSESE 1/256 S19 BT. The found J.H.N. rebar bears N32\*31'38"E, 3.63 ft. dsit.

I did not accept the found J.H.N. rebar as the true position for the SW—SE—SE 1/256 as it did not fall within positional tolerance.

Painted red the scribed faces and 6 in. bands on the bearing trees. Attached Land Survey Monument and Bearing Tree signs. Set a 6 ft. galvanized steel guard post 3 ft. South and East, with Land Survey Monument and Property Boundary decals attached.




Date of Fieldwork: 6/20/2007

Survey crew: Steve Boyer, Tom Hommel Magnetic declination: 20° East assumed

Equipment used: Hand compass and loggers tape

U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211



Lincoln Office of Clerk and Recorder, County of ....

208446 BOOK: CCR CCGR'S

PAGE: 11179 Pages: 1

STATE OF MONTANA LINCOLN COUNTY


RECORDED: 01/03/2008 2:06 KOI: CC&R'S

FEE: \$0.00 TO: FILED

TAMMY D. LAUER CLERK AND RECORDER
FEE: \$0.00 BY JULY Blondall Death

Cross Index No. Q.75-4.25 T. 31N. R. 31W.

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet