CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

T31N R31W montana principal meridian G.L.O. notes book 8942 page 52 has an iron post 30" long, $2\frac{1}{2}$ " in diameter, 15" in the ground to bedrock in concrete with brass cap marked T31N R31W

1962

Did not find brass cap but found 3 bearing trees. It appears that the brass cap was knocked out when the road was widened. Set Corps of Engineers brass cap from location of braing trees.

9" fir bearing N81°E, 59 lks., marked T31N R31W S36 BT Bearing tree alive and still growing and presently 10" in diameter Found:

63 lks. from new corner

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: May 74

Set brass cap and two new bearing trees.


1) 8" tamarack bearing S57°30'W, 203 lks., marked T30N R31W S2 BT 2) 12" cattonwood bearing N49°W, 269 lks. marked T31N R31W S35 BT

Sketch of brass cap on reverse side.....

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

DIAGRAM OF CORNER: T3IN R3/W Surveyor's Seal James R. Staples certify that the information shown herein is true and N correct. amed K Staples S33 S36 Signature of Ground Party Chief NTAN JOHN C. ERICKSON 52 51 certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this **ТОНИ С** recordation form and approve the same. ERICKSON *30N* 3979 S = Corner recorded on the sheet rupo SURVE YOUNG Signature of Surveyor 39795 Registration Number

Office of Clerk and Recorder, County of ... This "corner record" was filed for record on the 28 day of _______ 19.27, was noted on the cross-index plat and is W012 in book No..... assigned page No. County Official Cross Index No. 221 3*j*N ... Т... Form 125-3690



Description of evidence found continued from page 1

Record: 10" fir bearing S6°E, 61 lks., marked 730N R31W S1 BT Found: Bearing tree alive and still growing and presently 12" in diameter

Record: 36" stump bearingS49°E, 70 lks., marked T30N R31W S1 BT Found: Stump still in tact bearing S47°E, and 67 lks. from new corner