

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

T31N R31W Montana Principal Meridian G.L.O. notes book 2826 page 6 has 4 ft. post 3" square 24" in the ground marked 1/4 on the north face. Found no evidence of the corner or bearing trees. Reset the corner by single proportion method.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: May '74

Set Corps of Engineers brass cap marked as shown on sketch on reverse side. Since the corner fell in Elsie Boothman's front yard just south of Hwy. 37 the brass cap was set 2" below the surface for preservation. Set one bearing tree and one bearing pole and tied to garage and house.

- 1) 10" fir bearing N10°E, 22 lks., marked 1/4 S25 BT
2) Power pole bearing S52°E, 160 lks., marked 1/4 S36 BT
3) Northwest corner of the Boothman house bearing S6°W, 54 lks.,
4) Northeast corner of the garage bearing S40°E, 132 lks.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See reverse side.....

Surveyor's Seal



I, James R. Staples, certify that the information shown herein is true and correct.


Signature of James R. Staples, Signature of Ground Party Chief

I, JOHN C. ERICKSON, certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of John C. Erickson, Signature of Surveyor

39795 Registration Number

DIAGRAM OF CORNER:



= Corner recorded on the sheet

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 28 day of Mar 19 89, was noted on the cross-index plat and is assigned page No. 4016, in book No. [blank]

County Official signature: [Signature]

